



OSHA REGULATED: NO

SIGNS AND SYMPTOMS OF EXPOSURE: Skin rash and sensation of fair skinned people.

MEDICAL CONDITIONS AGGRAVATED BY EXPOSURE: N/A

EMERGENCY & FIRST AID PROCEDURES: Wash for 15 minutes in case of eye contact. Call a physician immediately. Wash clothing with soap and water. Discard shoes. Clean skin with waterless hand cleaner, then wash with soap & water.

SECTION VII	PRECAUTIONS FOR SAFE HANDLING AND USE
-------------	---------------------------------------

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED: Stop leak. Pump to salvage area or tank. Absorb remaining on paper, sand, clay, earth, vermiculite, floor absorbent or other absorbent materials. Shovel into containers.

WASTE DISPOSAL METHOD: Use federal, state and local approved methods. PRECAUTIONS TO BE TAKEN IN STORAGE & HANDLING: Wear protective boots, goggles, gloves, long sleeve shirt and long pants to protect skin and eyes.

OTHER PRECAUTIONS: Provide ventilation from exhaust fans.

SECTION VIII	CONTROL MEASURES
--------------	------------------

RESPIRATORY PROTECTION: SELF-CONTAINED RESPIRATORS ARE RECOMMENDED.

VENTILATION: YES PROVIDE THOUGH USE OF EXHAUST FANS.

PROTECTIVE GLOVES: YES EYE PROTECTION: GOGGLES

OTHER PROTECTIVE CLOTHING OR EQUIPMENT: Long sleeve shirts, long pants & boots.

WORK/HYGIENIC PRACTICES: Isolated contact with skin can be cleaned off the skin by the use of waterless hand cleaners followed by washing with soapy water. Rinse & dry with paper towels. DO NOT use solvent.

SECTION IX	PART A
------------	--------

D.O.T Non-Hazardous